DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

September

September 5, 1995

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the ent of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

CSX Transportation System

FP.95-03-07

REPORT NG OFFICER (signature/title)

MAIL TO

Director of Railroad Safety Federal Railroad Administration Suite 440 North Tower 1720 Peachtree Road, NW Atlanta, Georgia 30309

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the oasic system or appliance of which it forms an essential part. E.g., assume-grounds naive a block signal to indicate a faise proceed causing corresponding indications of a tab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic
AB-Automatic block
ACS-Automatic block
ACS-Automatic cab signal
APB-Absolute permissive block
ATC-Automatic train control
ATS-Automatic train stop
CL-Culor light
CPL-Culor position light

E-Electric

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
BLOCK SYSTEMS	9/5/9	P62405 Train	#6 Sig	nal N. Boynton Beach,
2 INTERLOCKING MATIC				
3 AUTOMATIC SYSTEMS				
ATS ATC ACS OTHER (specify)				
OTHER (specify,				

NATURE AND CAUSE OF FAILURE CORRECTIVE ACTION TAKEN

On September 5, 1995 Train P62405 reported that train P62705 had a medium clear out of siding while P62405 had a clean signal down the main line.

Signal system was removed from service. Signal department personnel investigated the incident and discovered that vandals had damaged junction box causing the LBRG control to contact the LBDG control.

The junction box was repaired and operational test completed. Signal system was returned to service.

(If more space is required, continue on severse)