

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION			
FALSE PROCEED SIGNAL REPORT		DATE	4 March 1996
MAIL TO		REPORTING CARRIER (railroad & region or division)	
Mr. Tom McFarlin Signal & Train Control Specialist Federal Railroad Administration 1100 Main Street, Suite 1130 Kansas City, MO 64105		Burlington Northern Santa Fe Northern	
REPORTING OFFICER (signature/title)		Assistant Vice President Signals	

FEDERAL RAILROAD  
ADMINISTRATION

A failure should not be counted more than once in Items 2, 3 and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, each failure should be included in Item 1. Block System

- The following abbreviations may be used in the report
- |                                |                       |
|--------------------------------|-----------------------|
| A -Automatic                   | EM -Electromechanical |
| AB -Automatic block            | EP -Electropneumatic  |
| ACS -Automatic cab signal      | FP -False proceed     |
| APB -Absolute permissive block | MP -Manual block      |
| ATC -Automatic train control   | M -Mechanical         |
| ATS -Automatic train stop      | P -Pneumatic          |
| CL -Color light                | PL -Position light    |
| CPL- Color position light      | SA -Semiautomatic     |
| E -Electric                    | TC -Traffic Control   |

A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.

TYPE OF SYSTEM	DATE	LOCOMOTIVE OR TRAIN NUMBER	DEVICE THAT FAILED	LOCATION (City and State)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	3/1/96	BN8014	Track Circuit	Lohman MT
2 INTERLOCKING <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> AUTO <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> MATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Extra 8014 East waiting behind Absolute signal behind units 2267(lead)&2079(trail). While light engines were proceeding through block, crew observed absolute signal go to Green and back to red several times. Train crew reported improperly displayed signal(signal was clear for only a few seconds), and dispatcher talked crew by signal. Data logs at location indicate that H recovered for several seconds several times. Track circuits were checked and all were found properly adjusted. Shunt tests were made throughout block and all OK. We assume that there was a loss of shunt on light engines proceeding through block at 50M