FEDERAL RAILROAD ADMIII	1011011				
FALSE PROCEED SIGNAL REPORT			REPORT FOR (month/year)		
			09/18/96		
All railroads subject to Regulations of the Fed a false proceed signal report, original only, to within five days after a false proceed occurs. calendar month, a report showing "No Failures end of the month. Copies of this form will be furnished upon requested Railroad Administration, Office of Safe	the Federal Railroad A If no false proceed oc s" must be filed within uest to the Departmen	curs during any ten days after the	REPORTING CARRIER (railroad & region or division)		
MAIL TO			TRANSPORTATION		
Federal Railroad Admin. Suite 440, North Tower 1720 Peachtree Rd., NW Atlanta, Ga. 30309 A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part, E.g.; assume grounds cause a block signal to indicate a failse proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System. A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.			REPORTING CARRIER (signature/litle) General Manger Signal Maintenance The following abbreviations may be used in the report.		
			A-Automatic AB-Automatic blo ACS-Automatic co APB-Absolute per ATC-Automatic tr ATS-Automatic tr CL-Color light CPL-Color positio E-Electric	ab signal FP-False proceed rmissive block MB-Manual block ain control M-Mechanical ain stop P-Preumatic PL-Position light	
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)	
BLOCK SYSTEMS AB X APB TC	09/18/96	Train PO5017	Semaphore	Indianapolis Subdivision , IN	
2 INTERLOCKING MATIC REMOTE MANUAL					
³ AUTOMATIC SYSTEMS ATS ATC ACS					

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On September 18, 1996 Train PO5017 reported that when approaching and passing a clear Eastbound Signal at MP 102.5 that the Westbound signal at the same location was in the clear position.

Signal system was removed from service. Signal personnel performed operational test and determined that Semaphore blade was stuck in the clear position with hold clear mechanism and track relays deenergized.

Repairs to Semaphore signal were made and signals performed as intended.

Signal system was returned to service.

1. marke Strc 10/22/96

(If more space is required, continue on reverse)

4 OTHER(specify)