DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

FEDERAL RAILROAD

Director of Railroad Safety DM VICE TO AD Federal Railroad Administration City Center Square, Suite 1130 CCT -6 P2:23

1100 Main Street

Kansas City, MO

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified A = Automatic under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block AB = Automatic block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train ACS = Automatic Cab Signal approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which ATC = Automatic train control results in less restriction than intended.

APB = Absolute permissive

REPORT FOR (month/year)

DATE

September 1997

October 1, 1997

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad

1416 Dodge Street Omaha, Nebraska

Tucson Service Unit

REPORTING OFFICER (signature/title)

block ATS = Automatic train stop

CL = Color light CPL = Color position light E = Electric

EM = Electromechanical

EP = Electropneumatic

FP = False proceed MB = Manual block

M = Mechanical

P -= Pneumatic

PL = Position light SA = Semiautomatic

TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS DAB DAPB TC	9/29/97	SP 8007	Code Relay	Lasca, TX
2 INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL				
AUTOMATIC SYSTEMS ATS ATC ACS				
4 OTHER (Specify)				
NATURE AND CAUSE OF FAILURE/CORREC	CTIVE ACTION T	AKEN		

On September 29, 1997, at 04:40 CDST, on the Valentine Subdivision, at Lasca, Texas, eastbound 1ILAAV/23, on the main track, at mile pole 746.1, observed a green eastbound signal at the west end of Lasca, with a red eastbound signal at the east end of Lasca.

An investigation revealed a bad order 180 code relay at west end of Lasca was responding to 75 code.

The signal was restored to proper operation, and all applicable tests were performed.