| DEPARTMENT OF TRANSPORTATION  |                                  |  |   |                        |                           |   |
|---|----------------------------------|--|---|------------------------|---------------------------|---|
| FEDERAL RAILROAD ADMINISTRATION   |                                  |  |   |                        |                           |   |
| FALSE PROCEED SIGNAL REPORT   |                                  | DATE   | 01-15-98  |                        |                           |   |
| MAIL TO   |                                  | REPORTING CARRIER (railroad & region or division)                                    |   |                        |                           |   |
| Mr. Tom McFarlin Signal & Train Control Specialist Federal Railroad Administration 1100 Main Street, Suite 1130 Kansas City, MO 64105   |                                  | Burlington Northern Santa Fe Gallup Subdivision  REPORTING OFFICER (signature/title) |   |                        |                           |   |
|   |                                  |  |   |                        |                           |   |
|   |                                  | Asst Vice President Signal   |   |                        |                           |   |
| že.   |                                  |  |   |                        |                           |   |
| A failure should not be counted more than one under interms 1, 2 4; the failure should be classified under the basic system or appli which it forms an estectiful part. E.g.: assume grounds cause a b signal to indicate a false proceed causing corresponding indicatic cab signal system on each train approaching this point, such failt be included in Item 1. Block System  A false proceed failure is a failure of a system device or applianc indicate or function as intended which results in less restriction to intended. | ance of lock ons of a are should | A AB ACS APB ATC ATS CL CPL-   | wing abbreviations m -Automatic -Automatic block -Automatic cab sign -Absolute permissive -Automatic train cor -Automatic train sto -Color light Color position light -Electric | al<br>e block<br>ntrol | EM EP FP MP M P P L SA TC | Electromechanical -Electropneumatic -False proceed -Manual block -Mechanical -Pneumatic -Position light -Semiautomatic -Traffic Control |
| TYPE OF SYSTEM  |                                  | LOCOMOTIVE OR TRAIN<br>NUMBER  |   | DEVICE THAT<br>FAILED  | LOCATION (City and State) |   |
| 1 BLOCK SYSTEMS  AB  APB  x TC  | 1-03-98                          | H-BARC   |   | 2 E SIGNAL             | WEST                      | BACA, NEW MEXICO  |
| 2 INTERLOCKING AUTO   |                                  |  |   |                        |                           |   |
| MATIC   |                                  |  |   |                        |                           |   |
| 3 AUTOMATIC SYSTEMS   |                                  |  |   |                        |                           |   |
| ATS ATC ACS   |                                  |  |   |                        |                           |   |
| 4 OTHER (specify)   | 1                                |  |   |                        |                           | ·   |
| NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN   |                                  |  |   |                        |                           |   |

AT 2224 HOURS ON JANUARY 3, 1998, TRAIN H-BARGAL-1-03 WAS STOPPED AT THE 2E SIGNAL AT WEST BACA WAITING FOR TRAIN AHEAD TO CLEAR THE PLANT AT EAST BACA. WHEN THE TRAIN AHEAD CLEARED THE PLANT AT EAST BACA, THE 2E SIGNAL AT WEST BACA DISPLAYED A YELLOW OVER GREEN ASPECT. THIS SIGNAL SHOULD HAVE BEEN YELLOW OVER RED.

SIGNAL TESTS REVEALED THAT THIS COULD BE DUPLICATED. THE PROBLEM WAS FOUND TO BE AN AAR WASHER HAD FALLEN DOWN BETWEEN TWO TERMINALS ON THE BACK OF THE H-2 MECHANISM AT EAST BACA. THIS WASHER BRIDGED TWO TERMINALS THEREBY FALSELY ENERGIZING THE 2E SIGNAL AT WEST BACA.

THE WASHER WAS REMOVED AND SIGNAL SYSTEM RESTORED.