T. marke SATC

| DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION | | | | | | REPORT FOR (month/year) March 1998 | |
|---|---|---|---|---|---|---|--|
| #13/98 FALSE PROCEED SIGNAL REPORT | | | | | - | March 30, 1998 | |
| a false proceed a within five days calendar month, end of the month. | ignal report after a fals a report sho | e proceed occu wing "No Fail | rs. If no false wres" must be | rad Administration sheal Railroad Administration sheal rocked occurs during filed within ten days Department of Transagton, D.C. 20598 | ation any after the | Norfolk Southern Corpo Division - Illinois | |
| MAIL TO | - | | | | 7 | | |
| • | | 16th Floor | - Suite 10 | | 1 | REPORTING OF FIGER (#IANA | ture/title) |
| L | 100 Alabama Street, SW Atlanta, GA 30303-3104 | | | | | Chief Engineer - Western Region Communications & Signal Dept. | |
| should be classified part. E.g.; causing corresponding point, such | fied under to assume grounding indic failures sho | he basic system unds cause a bi ations of a cah und be included failure of a sy | m or appliance lock signal to alignal system d in item 1, Bl stem, device 9 | r appliance to indica | essen- red A ching AC AP a oc AT C C CP | e following abbreviations may A—Automatic B—Automatic block S—Automatic cab signal B—Absolute permissive block C—Automatic train control S—Automatic train atop L—Color light L—Color position light E—Electric | EM-Electromechanics EP-Electropneumatic FP-False proceed |
| TYPE OF SYSTEM | | | DATE | LOCOMOTIVE NUMBER | DEVICE TH FAILED | | city and etate) |
| BLOCK SYSTE | MS APB | Хтс | 3/16/98 | 8945-6678 | poleline | Clymers, IN | |
| 2 INTERLOCKIN | | MANUAL | | | nei Pen | ART TO VICE THANKS | Onto Ni . |
| 3 AUTOMATIC S | YSTEMS | ACS | | | en er er allegen er er er er er | APR to mos | and the second s |
| | | | | | | | |

At approximately 3:45 PM, Train No. 183 with Engineer and Conductor , running westbound, reported receiving a clear signal at the East End Clymers and then a stop signal at the West End Clymers. Being in radio contact with opposing Train D93 west of Clymers, they were aware of the false signal and were able to stop before passing the stop signal.

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Signal personnel were called to investigate and found from TC loggers that there was indication of a westward signal lined at West End Clymers, not requested by the dispatcher, at the time that Train 183 saw the clear at East End Clymers. In the field, the same scenario was set up and proved that a westward clear was displayed at East End Clymers while a stop was displayed at West End Clymers. The cause was a falsely energized 500 ohm relay (LAYGP) at West End Clymers which resulted in the improper pole change back to East End Clymers. The relay was falsely energized by three volts caused by two separate line wraps in two different spans within the plant at West End Clymers. The LAYGP also tumbled down the eastward signals on Train D93 and gave the false indication of a westward signal at West End Clymers.

The wraps were corrected and the system retested to verify proper operation. The line wires involved were properly slacked and tied in. It was suspected, but never proved, that a truck had hit a pole and caused at least one of the wraps. High winds in this area on previous days were suspected of causing the first wrap. Neither wrap on its own would have caused this problem.