DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed s report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten after the end of the month.	If no
Copies of this form will be furnished upon request to the Department of Transportation, Federal Rai Administration, Office of Safety, Washington, D.C. 20590.	ilroad

MAIL TO

Director of Railroad Safety Federal Railroad Administration City Center Square, Suite 1130 1100 Main Street Kansas City, MO 64105-2112

REPORT FOR (month/year) December 1998 DATE January 4, 1999 REPORTING CARRIER (railroad & region or division) Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska Houston Service Unit REPORTING OFFICER (signature/title)

Chief Engineer-Signals The following abbreviations may be used in the report:

MANSAU CHI HALL

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified A = Automatic under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block AB = Automatic block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train ACS = Automatic Cab Signal approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which ATC = Automatic train control results in less restriction than intended.

APB = Absolute permissive

block

ATS = Automatic train stop CL = Color light

CPL = Color position light E = Electric

EM = Electromechanical

EP = Electropneumatic FP = False proceed

MB = Manual block

M = Mechanical

P -= Pneumatic

PL = Position light

SA = Semiautomatic TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS AB APB TC	12/18/98	UP 9455 W	None	Houston, TX
INTERLOCKING AUTOMATIC REMOTE MANUAL				
AUTOMATIC SYSTEMS □ ATS □ ATC □ ACS				
OTHER (Specify) NATURE AND CAUSE OF FAILURE/CORR	ECTIVE ACTION T	AVEN		

On December 18, 1998, at 09:30 CST, at Tower 26 on the Terminal Subdivision, in Houston, Texas, at mile post 360.69, westbound IEWLBB 18, on Main Track #2, reported westbound signal #70 was green and the next westbound signal #59 was red.

An investigation revealed the yellow/green control wires for signal #70 were reversed.

The signal system was restored to proper operation, and all applicable tests were performed.

(If more space is required, continue on reverse)