

**FALSE PROCEED SIGNAL REPORT**

REPORT FOR (month/year)

04/11/2000

REPORTING CARRIER (railroad and region or division)

**CSX  
Transportation  
Train Control**

REPORTING CARRIER (signature/title)

Director Signal Reliability

All Railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.  
Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

**MAIL TO**

Federal Railroad Admin.  
61 Forsyth St SW  
Suite 16T20  
Atlanta, Ga. 30303

A failure should not be counted more than one time in items 1, 2, 3, and 4, the failure should be classified under the basic system or appliance of which it forms an essential part. E.g., assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A-Automatic
- AB-Automatic block
- ACS-Automatic cab signal
- APB-Absolute permissive block
- ATC-Automatic train control
- ATS-Automatic train stop
- CL-Color light
- CPL-Color position light
- E-Electric
- EM-Electromechanical
- EP-Electropneumatic
- FP-False proceed
- MB-Manual block
- M-Mechanical
- P-Pneumatic
- PL-Position light
- SA-Semiautomatic
- TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
<b>1 BLOCK SYSTEMS</b> <input type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC				
<b>2 INTERLOCKING</b> <input type="checkbox"/> AUTO-MATIC <input checked="" type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL	04/11/2000	H89611	None	E.E. Quinimont Quinimont, WV
<b>3 AUTOMATIC SYSTEMS</b> <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
<b>4 OTHER (specify)</b>				

**NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN**

At approximately 1515 hours on April 11, 2000, the crew of H89611 reported that they had received a Medium Clear signal at MP 377 while proceeding eastbound out of the siding at E.E. Quinimont into a Stop signal at Backus MP 371. The signal should have displayed a Medium Approach. Signal personnel were dispatched, verified the false proceed indication, and subsequently removed the signals from service.

Further investigation revealed that the R270 DR relay was improperly energized by a wire which ran directly to the BH-6 battery buss, effectively removing the # 1 reverse polar contact of the R268 HDR from the circuit. This permitted the R270 DR relay to be energized when the R270 signal was requested without checking the aspect displayed at Backus.

The wiring error was corrected and signals were returned to service following operational testing.

The cause was found to be improper operational testing following field wiring changes.

