FALSE PROCEED SIGNAL REPORT

aitroads subject to Regulations of the Federal Railroad Administration shall submit se proceed signal report, original only, to the Federal Railroad Administration in five days after a false proceed occurs. If no false proceed occurs during any order month, a report showing "No Failures" must be filled within ten days after the of the month.

es of this form will be furnished upon request to the Department of Transportation, eral Railroad Admininstration, Office of Safety, Washington, D.C. 20590

IL TO

Federal Railroad Admin. 61 Forsyth St SW Suite 16T20 Atlanta, Ga. 30303 REPORT FOR (month/year) 05/11/2000

REPORTING CARRIER (railroad and region or division)

CSX Transportation Train Control

REPORTING CARRIER (signature/title)

Director Signal Reliability

aflure should not be counted more than one time in items 1, 2, 3, and 4; the failure ruid be classified under the basic system or appliance of which it forms an essenpart, E.g.; assume grounds cause a block signal to indicate a false proceed issing corresponding indications of a cab signal system on each train approaching a point, such failures should be included in item 1, Block System.

alse proceed failure is a failure of a system, device or appliance to indicate or action as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic block
AB-Automatic block
ACS-Automatic cab signal
APB-Absolute permissive block
ATC-Automatic train control
ATS-Automatic train stop
CL-Color light
CPL-Color position light

EM-Electromechanical
EP-Electropneumatic
FP-False proceed
MB-Manual block
M-Mechanical
P-Pneumatic
PL-Position light
SA-Semiautomatic
TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
BLOCK SYSTEMS AB APB X TC	05/11/2000	IHB Run 518	Design	CP Francisco Blue Island , IL
INTERLOCKING AUTO-MATIC REMOTE MANUAL				
AUTOMATIC SYSTEMS ATS ATC ACS				
OTHER (specify)				

ATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On Thursday, May 11, 2000 at approximately 1022 hours Indiana Harbor Belt (IHB) Train Run 518 received a lestricting signal at CP Francisco MP DC 14.9 (IHB MP 15.4) to proceed west on Track 1. At the same time, astbound IHB Train NP 11 accepted an opposing approach signal at CP 123 (IHB MP 17.5) to proceed east on rack 1. Each train proceeded into the block until they viewed the opposing train and stopped. The signals were emoved from service and Train Control personnel were dispatched.

Further investigation revealed that the false proceed was caused when the Call-On feature was initiated by ne dispatcher, which permitted a Restricting signal to be displayed at CP Francisco with an opposing signal already ned into the block.

Temporary wiring changes were made to disable the Call-On circuit, and signals were returned to service ollowing operational testing.

The cause was found to be a design error.

MAY 26 2000
ATLANTA, GEORGIA

GPO 929-925