

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

08/20/2000

All Railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.
Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

REPORTING CARRIER (railroad and region or division)

CSX
Transportation
Train Control

MAIL TO

Federal Railroad Admin.
61 Forsyth St SW
Suite 16T20
Atlanta, Ga. 30303

REPORTING CARRIER (signature/title)

Director Signal Reliability

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report

A-Automatic	EM-Electromechanical
AB-Automatic block	EP-Electropneumatic
ACS-Automatic cab signal	FP-False proceed
APB-Absolute permissive block	MB-Manual block
ATC-Automatic train control	M-Mechanical
ATS-Automatic train stop	P-Pneumatic
CL-Color light	PL-Position light
CPL-Color position light	SA-Semiautomatic
E-Electric	TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEMS <input checked="" type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC	08/20/2000	CP522	CP9 SB Sig. #2 Track	Tonawanda, NY
2 INTERLOCKING <input type="checkbox"/> AUTO-MATIC <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On August 20, 2000, the Train Crew on southbound CP 522 observed the southbound signal on #2 track at CP9 displaying an Approach Medium aspect with a Stop aspect at the next signal at CP8. The Signal at CP9 should have displayed an Approach aspect. The signal was removed from service and Train Control personnel were dispatched.

The cause was found to be open line wires which were twisted together by a tree leaning into the pole line.

The tree was cut away, line wire was repaired, signal and switch checks were made with no exceptions, and the signals were returned to service. The cause was determined to be external damage from the tree to the pole line wire.

3