DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety **Federal Railroad Administration** 901 Locust Street Kansas City, MO 64106

00 JUL -3 P4:35

REPORT FOR (month/year)

June 2000

DATE

June 29, 2000

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, Nebraska

Houston Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report:

A = Automatic AB = Automatic block

ACS = Automatic Cab Signal APB = Absolute permissive block

ATC = Automatic train control ATS = Automatic train stop

CL = Color light CPL = Color position light

E = Electric

EP = Electropneumatic FP = False proceed MB = Manual block M = Mechanical P -= Pneumatic PL = Position light

EM = Electromechanical

SA = Semiautomatic TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
BLOCK SYSTEMS AB APB ATC	6/3/00	UP-1647	NONE	HOUSTON, TX
2 INTERLOCKING				
AUTOMATIC SYSTEMS ATS ATC ACS				
4 OTHER (Specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On June 3, 2000, at 14:50 CDT, at Houston, TX on the Terminal Subdivision at MP 366.30, the Dispatcher was able to line a route from CP LF369, on the #1 main to Bellaire Junction, with a hand throw switch on the #1 main, located south of CP LF369 in a reverse position.

An investigation revealed a design error. The Switch Correspondence Relay was not wired into the control for the southbound signal at CP LF369.

The signal system was restored to proper operation, and all applicable tests were performed.