DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

September 2000

September 11, 2000

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad

1416 Dodge Street Omaha, Nebraska

DATE

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no talse proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety Federal Railroad Administration 901 Locust Street Kansas City, MO 64106

North Little Rock Service Unit REPORTING OFFICER (signature/title)

SEP 15 A11:37

Chief Engineer-Signals The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4, the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal

APB = Absolute permissive block

ATC = Automatic train control ATS = Automatic train stop

CL = Color light

CPL = Color position light

EM = Electromechanical

EP = Electropneumatic FP = False proceed

MB = Manual block M = Mechanical

P -= Pneumatic PL = Position light

SA = Semiautomatic

E = Electric TC = Traffic Control LOCOMOTIVE **DEVICE THAT** TYPE OF SYSTEM DATE NUMBER **FAILED** LOCATION(city and state) **BLOCK SYSTEMS** 9/1 UP3074 NONE DEXTER JUNCTION, MO X TC □ APB INTERLOCKING ☐ AUTOMATIC REMOTE ☐ MANUAL **AUTOMATIC SYSTEMS** ☐ ATS □ ACS ☐ ATC OTHER (Specify)

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On September 1, 2000 at 5:48 CDT at Dexter Junction on the Jonesboro Subdivision, southbound MINPB 01 on the main track at mile pole 40.3 reported the southbound signal (4L) displaying a green aspect and as they proceeded they encountered the northbound LSV5O 01, a local with a single 4-axle unit, in the same block.

An investigation revealed an oil film was present on the rail between Dexter Junction and Bernie causing a loss of shunt. It is unknown as to the origin of the oil film and it is under investigation.

The oil film was removed and the signal system operated as intended.

CC Pungle FP00-6-6 9-15-00

(If more space is required, continue on reverse)