DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety
Federal Railroad Administration
901 Locust Street
Kansas City, MO 64106

FEDERAL

DATE

1416 Dodge Street Omaha, Nebraska

Union Pacific Railroad

REPORTING CARRIER (railroad & region or division)

Salt Lake Service Unit

The following abbreviations may be used in the report:

REPORTING OFFICER (signature/title)

O OCT 27 P12:0

Chief Engineer-Signals

CHCHEN

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

REPORT FOR (month/year)

October 2000

October 24, 2000

ACS = Automatic Cab Signal APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop CL = Color light

CPL = Color position light

EM = Electromechanical

EP = Electropneumatic

FP = False proceed MB = Manual block

M = Mechanical

P -= Pneumatic

PL = Position light

SA = Semiautomatic TC = Traffic Control

			E = Electric	TC = Traffic Control
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
BLOCK SYSTEMS TC	10/20/00	UP4051	NONE	EVANSTON, WY
2 INTERLOCKING				
AUTOMATIC SYSTEMS ATS ATC ACS				
OTHER (Specify) NATURE AND CAUSE OF FAILURE/CORREC				

On October 20, 2000 at 10:45 MDT in Evanston, Wyoming on the Evanston Subdivision, eastbound ZLAAP 18 was on Track 2 and reported eastbound signal 917.4 was green with the switch at MP 916.8 lined against him.

An investigation revealed the shunt fouling wires from the switch circuit controller were not connected to the rail on one side.

The signal system was restored to proper operation, and all applicable tests were performed.

CC: Vancouver 10-22/10

(If more space is required, continue on reverse)