

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)
03/10/2001

All Railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month. Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

REPORTING CARRIER (railroad and region or division)

**CSX
Transportation
Train Control**

MAIL TO

Federal Railroad Admin.
61 Forsyth St SW
Suite 16T20
Atlanta, Ga. 30303

REPORTING CARRIER (signature/title)

Director Signal Reliability

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block System.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A-Automatic
- AB-Automatic block
- ACS-Automatic cab signal
- APB-Absolute permissive block
- ATC-Automatic train control
- ATS-Automatic train stop
- CL-Color light
- CPL-Color position light
- E-Electric
- EM-Electromechanical
- EP-Electropneumatic
- FP-False proceed
- MB-Manual block
- M-Mechanical
- P-Pneumatic
- PL-Position light
- SA-Semiautomatic
- TC-Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1 BLOCK SYSTEM <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	03/10/2001	V829-10	Phantom Aspect	D Tower Grafton, WV
2 INTERLOCKING <input type="checkbox"/> AUTO-MATIC <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On Saturday evening March 10, 2001 Eastbound train V829-10 running from the Fairmont Sub-division to D Tower at Grafton reported a Restricting Signal. Initial investigation revealed that the signal had not been requested by the Jacksonville dispatcher. Signals were removed from service pending investigation. The field investigation revealed that the signal was at stop but was sunlit. The team refocused the signals and installed an additional screening material as the signals already had Phankill installed. We are reporting this event but we do not consider this to be a false proceed.

