DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION FALSE PROCEED SIGNAL REPORT			REPORT FOR (month/year)  Feb-02  DATE	
			19-Feb-02 REPORTING CARRIER  Norfolk Southern Corporation	
MAIL TO  Mr. Michael Woods  Federal Railroad Administration  16th Floor - Suite 16T20  100 Alabama Street, SW  Atlanta, GA 30303-3104			Division: Pocahontas  REPORTING OFFICER  Chief Engineer - Eastern Region  Communications & Signal Department	
				cations & Signal Department
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
BLOCK SYSTEMS  AB  APB  X TC  AUTO-	2/17/2002	NS 9003	Relay Circuit	Matewan, WV
INTERLOCKING MATIC				
REMOTE MANUAL	-		<del> </del>	
AUTOMATIC SYSTEMS				
ATS ATC ACS				
OTHER (specify)  NATURE AND CAUSE OF FAILURE / CORRECTIVE AG	TION TAVEN			

received a westbound approach At 12:42 a.m. on 2/17/02, train U72U616 with engineer and conductor aspect on the 8LR signal at Control Point Ought-One, MP N445.5 on the Pocahontas Division, when the 8LR signal located at MP D0.6 should have displayed a Stop aspect.

The problem was duplicated during testing and found to be a foreign voltage on the LC08H relay, falsely energizing the relay which allowed the yellow aspect to be displayed on the "A" signal head. Signal 8LR is a color light signal. The short was found in the LC08H circuit in the main shelter at CP Ought-One. This is a TC Green wired bungalow and a TC Green wire had shorted to local battery. The defective wire was replaced in the circuit, eliminating the foreign voltage. In addition, the location is scheduled to be upgraded to new electronic equipment in March, 2002.

OPTIONAL FORM 99 (7-90)		3/12/02
FAX TRANSMIT	TAL	# of pages > / - /
Tohn Reynolds	From	
Dept./Agency DOT/FRA	Phone #	
610.521-8225	Fax #	· .
NSN 7540-01-317-7368 5099-10		RAL SERVICES ADMINISTRATION

