DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION					
FALSE PROCEED SIGNAL REPORT		DATE April 16, 2003			
MAIL TO	REPORTING CARRIER (railroad & region or division)				
Mr. James Drake Signal & Train Control Specialist Federal Railroad Administration 901 Locust Street - Suite 464 Kansas City, MO 64106		Burlington Northern Santa Fe Railway			
		Assistant Vice President Signal BNSF Railway			
james drake@fra.dot.gov corene.macmahon@fra.dot.gov		REPORTING OFFICER (signature/title)			
A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failure should be included in Item 1. Block System A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.		The following abbreviations may be used in the report			
		A -Automatic		EM	-Electromechanical
		AB -Automatic block		EP	-Electropneumatic
		ACS -Automatic cab signal		FP	-False proceed
		APB -Absolute permissive block		MP	-Manual block
		ATC -Automatic train control		M	-Mechanical
		ATS -Automatic train stop		P	-Pneumatic
		CL -Color light		PL	-Position light
		CPL- Color position light	t	SA	-Semiautomatic
		E -Electric		TC	-Traffic Control
TYPE OF SYSTEM DA	ATE	LOCOMOTIVE OR TRAIN NUMBER	DEVICE THAT FAILED	LOCATION (City and State)	
1 DECCROTOTE	1/05 003	Gateway Railroad Switch Engine	54 LB Signal	Kansas City, MO	
2 INTERLOCKING AUTO MATIC					
3 AUTOMATIC SYSTEMS ATS ATC ACS					
4 OTHER (specify)					
NATURE AND CAUSE OF FAILURE/CO	RRF	ECTIVE ACTION T	AKEN		
A Gateway Railroad switch engine crew on	Anri	il 5 2003 reported o	heerving red c	ver gr	een aspect at the
A Gateway Kanroad Switch engine crew on	Apn	II 5, 2005 reported 0	disciving read	ed sen	con aspect at the
54 LB Signal, and stated they stopped short	oi u	ie next signal (30L)	displaying a n	eu aspi	cci. Signais were p

A Gateway Railroad switch engine crew on April 5, 2003 reported observing red over green aspect at the 54 LB Signal, and stated they stopped short of the next signal (50L) displaying a red aspect. Signals were put to stop and traffic was suspended over said route. Investigation revealed that report by crew was factual. Investigation also revealed that during a cut over March 27, 2003 changes had been made to correct a wiring error, but related signals were not re-tested. Circuit changes were made to correct the wiring error and all signals were tested without exceptions. Signal 54 LB put back into service April 5, 2003.