

FP 2003-5-9

DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION FALSE PROCEED SIGNAL REPORT - ALLEGED		DATE <input type="checkbox"/> Nov. 4, 2003
MAIL TO Mr. James Drake Signal & Train Control Specialist Federal Railroad Administration 901 Locust Street - Suite 464 Kansas City, MO 64106 <u>james.drake@fra.dot.gov</u>		REPORTING CARRIER (railroad & region or division) Burlington Northern Santa Fe Railway Texas Division / Red River Valley Subdivision REPORTING OFFICER (signature/title) AVP Signal

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failure should be included in Item 1. Block System

A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.

- The following abbreviations may be used in the report
- | | |
|--------------------------------|-----------------------|
| A -Automatic | EM -Electromechanical |
| AB -Automatic block | EP -Electropneumatic |
| ACS -Automatic cab signal | FP -False proceed |
| APB -Absolute permissive block | MP -Manual block |
| ATC -Automatic train control | M -Mechanical |
| ATS -Automatic train stop | P -Pneumatic |
| CL -Color light | PL -Position light |
| CPL -Color position light | SA -Semiautomatic |
| E -Electric | TC -Traffic Control |

TYPE OF SYSTEM	DATE	LOCOMOTIVE OR TRAIN NUMBER	DEVICE THAT FAILED	LOCATION (City and State)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	10/21/03	Q LACAUG 618	None found	Estelline, TX
2 INTERLOCKING <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/> AUTO MATIC				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

ALLEGED

Dispatcher reported two EB trains at East Estelline. The 1st EB train had a Red signal at E. Estelline and was talked by the signal. The 2nd train also had a Red signal at E. Estelline and was being talked by the signal when the signal went Green. The 1st EB train advised the 2nd EB train that the signal at F. Estelline should not be Green because the rear of their train just passed the approach signal at MP 233.6. The signal at F. Estelline for the 2nd EB train should have been Yellow.

After extensive testing, the alleged false proceed could not be duplicated. After consultation with BNSF Signal Engineering and GE Global Signaling (coded track equipment manufacturer) it was decided to change out the coded track systems at both the intermediate signal 233.6 and E. Estelline. In addition, a recorder was installed at intermediate signal 233.6 and a 216DL recorder module inserted into the newly installed Electro-Code 4H at E. Estelline. Operating Department personnel and the engineers on both trains are aware of our testing results and remedial actions.

(If more space is required continue on reverse)

FRA F6180-14