DEPARTMENT OF TRANSPORTATION							
FEDERAL RAILROAD ADMINISTRATION			· · · · · · · · · · · · · · · · · · ·				
FALSE PROCEED SIGNAL REPORT	D.	ATE	12-29-2003				
MAIL TO		REPORTING CARRIER (railroad & region or division)					
W 1 5 L		Burlington Northern Santa Fe Railway					
Mr. James Drake Signal & Train Control Specialist							
Federal Railroad Administration							
901 Locust Street - Suite 464 Kansas City, MO 64106							
james drake@fra.dot.gov		REPORTING OFFICER (signature/title)					
		/ Manager Signal					
		/ Manager Signal					
A failure should not be counted more than one time in items 1, 2, 3,			The following abbreviations may be used in the report				
and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.: assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failure should be included in Item 1. Block System A false proceed failure is a failure of a system device or appliance to indicate or function as intended which results in less restriction than intended.		A -Automatic			EM	-Electromechanical	
		AB -Automatic block		EP	-Electropneumatic		
		ACS -Automatic cab signal			FP	-False proceed	
		APB -Absolute permissive block			MP	-Manual block	
		ATC -Automatic train control			M	-Mechanical	
		ATS	-Automatic train st	ο υ	P	-Pneumatic	
		CL	-Color light	•	PL	-Position light	
		CPL-	Color position light	i	SA	-Semiautomatic	
			-Electric		TC	-Traffic Control	
TYPE OF SYSTEM D		OCOM	OTIVE OR TRAIN	DEVICE THAT FAILED	LOCA	TION (City and State)	
1 BLOCK SYSTEMS 13	2-29-	UMBE	·	PAILED	East V	ictorville.	
☐ AB ☐ APB ☐ TC 2	2003						
2 INTERLOCKING AUTO MATIC							
3 AUTOMATIC SYSTEMS							
ATS ATC ACS							
4 OTHER (specify)							
NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTIO	N TAKEN	ı Nı	מ מור בייקוס איל פו ס	A C ย A A			
General Order to remove signals not conforming to rule 9.1.11 was removed on the Cajon Subdivision. The East Victorville signals had been due to be converted							
in a cutover planned earlier in the year but had been re-scheduled several times due to train traffic volumes. When Signal Supervisor completed spreadsheets to a							
master list this location was shown as completed but had not been done. Red over flashing yellow aspects were converted to Red over Yellow and routes were tested and system returned to service.							
						1	
			OUTHVIELD	MAA			
		Ų¥	Manyn iv	L EUE!			
(If more space is required continue on reverse)		•				FRA F6180-14	