

DEPARTMENT OF TRANSPORTATION  
 FEDERAL RAILROAD ADMINISTRATION  
 FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

April, 2003

DATE

April 8, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad  
 1416 Dodge Street  
 Omaha, NE - 68179

Houston

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety  
 Federal Railroad Administration  
 901 Locust Street  
 Kansas City, MO 64106

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

- A = Automatic
- AB = Automatic block
- ACS = Automatic Cab Signal
- APB = Absolute permissive block
- ATC = Automatic train control
- ATS = Automatic train stop
- CL = Color light
- CPL = Color position light
- E = Electric
- EM = Electromechanical
- EP = Electropneumatic
- PP = False proceed
- MB = Manual block
- M = Mechanical
- P = Pneumatic
- PL = Position light
- SA = Semiautomatic
- TC = Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	4/4/03	UP2205	NONE	Missouri City, CA
2 INTERLOCKING <input type="checkbox"/> AUTOMATIC <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
3 AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4 OTHER (Specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On April 4, 2003, at 08:50 CST, in Missouri City, TX, on the Gladwin Subdivision, eastbound RBMBD-02, at mile post 20.60, reported the eastbound intermediate signal at 20.60 was green, and the next eastbound absolute signal at SA019 was red over yellow.

An investigation revealed that the polarity on the control circuit to eastbound signal 20.60 was reversed.

The signal system was restored to proper operation, and all applicable tests were performed.

(If more space is required, continue on reverse)