## **DEPARTMENT OF TRANSPORTATION** FEDERAL RAILROAD ADMINISTRATION

## FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety Federal Railroad Administration 901 Locust Street Kansas City, MO 64106

REPORT FOR (month/year)

April, 2003

DATE

April 28, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

Roseville

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal

APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop

CL = Color light

CPL = Color position light E = Electric

EM = Electromechanical

EP = Electropneumatic

FP = False proceed

MB = Manual block

M = Mechanical

P -= Pneumatic

PL = Position light SA = Semiautomatic

TC = Traffic Control

					1C 11ame Condo
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED		LOCATION(city and state)
BLOCK SYSTEMS  AB APB X TO	4/23/03	(WB) UP 9318 (EB) UP 4961	Code Xmit Relay		Kramm, CA
2 INTERLOCKING □ AUTOMATIC □ REMOTE □ MANUAL		КАІ	.03 	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	
3 AUTOMATIC SYSTEMS □ ATS □ ATC □ ACS		NSAS	AY		
4 OTHER (Specify)		R A.IIQ		ં 💆	
NATURE AND CAUSE OF FAILURE/CORREC	TIVE ACTION TA			<u> </u>	
		NON .	34	AD AD	

On April 23, 2003, at 13:20 PDT, in Kramm, CA, on the Canyon Subdivision two incidents happened. Westbound WDMELB/22 reported westbound signal at 216.10 was yellow then turned green until he passed it. and the next absolute signal at CPF215 was red over yellow.

Eastbound IOASC/22 reported that eastbound absolute signal at CPF213 was yellow, turned green, and then back to yellow while he approached the signal.

An investigation revealed a bad 75 code transmitter relay common to both track circuits feeding from CPF215.

The code relay was replaced, and all applicable tests were performed.