DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety Federal Railroad Administration 901 Locust Street Kansas City, MO 64106

REPORT FOR (month/year)

August, 2003

DATE

August 6, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

Tucson Service Unit

REPORTING OFFICER (signature/title)

Chief Engineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended,

A = Automatic

AB = Automatic block

ACS = Automatic Cab Signal APB = Absolute permissive block

ATC = Automatic train control

ATS = Automatic train stop

CL = Color light

F = Flastrio

CPL = Color position light

EM = Electromechanical

EP = Electropneumatic FP = False proceed

MB = Manual block

M = Mechanical

P -= Pneumatic

PL = Position light

SA = Semiautomatic

				E - Electric	IC = Iranic Control
TYPE OF SYSTEM		DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS AB APB	Х тс	08/02/03	UP 4425	none	Tornillo, TX
2 INTERLOCKING □ REMOTE	☐ AUTOMATIC				
3 AUTOMATIC SYSTEMS ATS ATC	ACS				
4 OTHER (Specify)					

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On August 02, 2003, at 07:13 CDT, in Tornillo, TX, on the Valentine Subdivision, eastbound ILBNS 31, on the side track, at MP 792.5, reported the eastbound signal in the siding went green for several seconds before down grading to yellow, with a train ahead of him east of Tornillo.

An investigation revealed rodent damage to the circuit wiring caused a battery wire to intermittently false pick the EDR relay giving a green signal.

The damage was repaired and all applicable tests were performed.

(If more space is required, continue on reverse)

FORM FRA F 6180-14 (6-72)