DEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590.

MAIL TO

Director of Railroad Safety
Federal Railroad Administration
901 Locust Street
Kansas City, MO 64106

REPORT FOR (month/year)

August, 2003

DATE

September 10, 2003

REPORTING CARRIER (railroad & region or division)

Union Pacific Railroad 1416 Dodge Street Omaha, NE - 68179

North Little Rock Service Unit

REPORTING OFFICER (signature/title)

hef Bigineer-Signals

The following abbreviations may be used in the report:

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g., assume grounds range a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

A = Automatic AB = Automatic block

ACS = Automatic Cab Signal

APB = Absolute permissive block ATC = Automatic train control

ATS = Automatic train stop

CL = Color light CPL = Color position light EM = Electromechanical EP = Electropneumatic

FP = False proceed
MB = Manual block
M = Mechanical

P -= Pneumatic
PL = Position light

SA = Semiautomatic TC = Traffic Control

		_		E = Electric	IC = Traine Control
TYPE OF SYSTEM		DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION(city and state)
1 BLOCK SYSTEMS AB APB	X TC	09/04/03	UP 1674	None	Mitchellville, AR
2 INTERLOCKING □ REMOTE	☐ AUTOMATIC ☐ MANUAL				
3 AUTOMATIC SYSTEMS ATS ATC	ACS				
4 OTHER (Specify)		}			

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On September 04, 2003, at 16:14 CDT, in Mitchellville, AR, on the McGehee Subdivision, southbound MPBBT 04, at MP 393.90, reported southbound signal A394 was green, with the next block south occupied by (light power) LWB71-04 – UP1674 & UP912.

An investigation revealed the CAD Log verified a loss of shunt by the LWB71-04.

All applicable tests were performed.

**O3 SEP 15 P P SOL NOA CONTINUE ON reversion (If more space is required, configure on reverse)

GPO 929-92