SEPARTMENT OF TRANSPORTATION FEDERAL RAILROAD ADMINISTRATION

## FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year) October 25, 1995

November 21, 1995

All railroads sunject to Regulations of the Federal Railroad Administration shall submit a laise proceed signal report, original only, to the Federal Railroad Administration within five days after a laise proceed occurs. If no faise proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the gold of the month. end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

REPORTING CARRIER (railroad & region or division)

Long Island Rail Road

VAIL 200

Department of Transportation Federal Railroad Administration Office of Safety, RA-613 Washington, D.C. 20590

REPORTING OFFICER (signature/title)

Frederick E. Smith, P.E. Chief Engineer

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g., assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a can signal system on each train approaching this point, such failures should be included in item 1. Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic AS-Automatic block ACS-Automatic cab signal APB-Absolute permissive block MB-Manual block ATC-Autometic train control ATS-Automatic train stop CL-Culor light CPL-Color position light

E-Electric

FM-Electromechanical EP-Electropneumetic FP-False proceed M-Mechanicai P-Pneumatic PL-Position light SA-Semiautomatic TC-Treffic control

TYPE OF SYSTEM		DATE	LOCOMOTIVE	DEVICE THAT	LOCATION (city and state)
BLOCK SYSTEMS	Tτc				
INTERLOCKING	MANUAL	10/25/95	1624	Signal Circuitry	Divide Interlocking
AUTOMATIC SYSTEMS	ACS				
OTHER (specity)					

NATURE AND CAUSE OF FAILURE CORRECTIVE ACTION TAKEN.
At Divide Interlocking, an eastbound route was displayed for Train 1624, to route the train from Main Line #2 Track, 3-2E Signal, to Station Track #2, 3-2W Signal. In addition, a stored route had been established for Train RF-31 from Station Track #1, 3-1W Signal to Main Line #2, 3-2E Signal. The track circuit 3-AlTR, which is the first circuit east of 3-2E Signal on Main Line #2, momentarily de-energized (flipped). This caused the previously established route (3-2E to 3-2W) to reset, enabling the stored route (3-1W to 3-2E) to be established via a back to train stick feature. Signal 3-1W then displayed a restricting aspect.

## CORRECTIVE ACTIONS:

- The back to train stick features were disabled.
- Conflicting stored route operation was prohibited via a computer warning on the "CRT" and written procedures from the Transportation Department.

'Il more space is required, continue on reverse;

GPO 92 9-92 5