11/10/95 11:32 EJ&E MA DEPARTMENT OF TRANSP		OF WAY → 312	886 9634   REPORT	FOR (montaryear)	10.882 PØØ5/0Ø5	
FEDERAL RAILROAD ADMIN			NOV	). <u>2 1995</u>		
FALSE PROCEED SIGNAL REPORT				NOJ. 9 1995		
a support to Approxitoss of the Poppine Religious administrative Foppine Religious Administratives within 13 days after a cause on the form with a furnished times regress to the Descriment of Poppine William Co. 20190			ELGI	TING CARRIER (routross  JOLIET  STERJ 508 DIO	· Exeter Ry	
REGIONAL DIRECTOR OF RAILROAD FEDERAL RAILROAD ADMINIST 111 NORTH CANAL STREET CHICAGO, ILLINOIS 60606	SAFETY			TING OFFICER (signatur		
e should not be counted more than one time in a d under the basic system or appliance of which cause a poice stemal to indicate a faise proceed of your on each train approaching this point. Supposed failure is a failure of a system device a which restrict is less restriction than intended.	at infind an examination (actions and	conung indication buid be included in	nould be : assume A-A sofs can AB-A n item 1. ACS-A APB-A ATC-A CL-C CPL-C	lowing sobreviations may utomatic block utomatic cap signal block utomatic cap signal utomatic train scontrol utomatic train stop block ight block ight block ight block ight blocking the clarence with the clare	EM-Electromechanica; EP-Electromeumatic FP-Faise proceed MP-Manusi block M-Mechanica; P-Presimon light SA-Semiautomatic TC-Traffic Control	
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT	LOCATION	errà dua mara)	
OCK SYSTEMS  AB APB TC  AUTO-			TRACK	VERNON HILLS	TUNOIS	
REMOTE MANUAL	11/2		REWY	VELSON	,	
ATS ATC ACS						
HER(specify)		-				

## TRE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

On subject interlocking, a track circuit BNWLP, in the fouling section is so arranged that when the Electric lock installed on the switch allowing movements from the siding onto the main and into interlocking limits is unlocked or opened 1/4" from full normal, the track circuit is de-energized. Once de-energized, it de-energizes a relay that is used as the OS track. All signals on all routes are effectively slotted off with the OS relay down.

Shunt fouling wires were inadvertently installed from the main to the fouling section. When the electric locks were unlocked or opened 1/4" from full normal, the track relay BNWLP remained energized through the OS track battery, not effectively slotting off all signals.

Shunt fouling wires were removed correcting the failure.