## DEPARTMENT OF TRANSPORTATION

FALSE PROCEED SIGNAL REPORT

## FEDERAL RAILROAD ADMINISTRATION

## REPORT FOR (month/year)

1	/97	
1	191	

## DATE

1/28/97

All railroads subject to Regulations of the Federal Railroad Administration shall submit a talse proceed signal report, original only, to the Federal Railroad Administration within five days after a talse proceed occurs. If no false proceed occurs during any calendar month, a report showing. No Failures! must be filed within ten days after the end of the month.

Wisconsin Central Ltd.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAR TO

REPORTING OF ICER (signature gille)

REPORTING CARRIER (railroad & region or division)

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the nasic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

A-Automatic AB-Automatic block ACS-Automatic cab signal

CPL-Color position light

E-Electric

APB-Absolute permissive block ATC-Automatic train control ATS-Automatic train stop CL-Color light

EM-Electromechanical EP-Electropneumatic FP-False proceed MB-Manual block M-Mechanical P-Pneumatic PL-Position light SA-Semiautomatic

			E-Elec	TC-Traffic control
TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT	LOCATION (city and state)
BLOCK SYSTEMS X AB APB TC	1/28/97		Signal 105.9	Sussex WI
INTERLOCKING MATIC				
ATS ATC ACS				
OTHER (specify)				

NATURE AND CAUSE OF FAILURE CORRECTIVE ACTION TAKEN

SA mechanism had improper polarity giving clear indication verses approach.

Mechanism changed out 1/27/97 rail gang working west of signal so circuit could not be tested.

Testman did not return to make final check after track was put back together.