

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

REPORT FOR (month/year)
September 1999

FALSE PROCEED SIGNAL REPORT

DATE
October 7, 1999

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false signal report, original only, to the Federal Railroad Administration within fifteen days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

REPORTING CARRIER (railroad & region or division)

National Railroad Passenger Corp.
30th Street Station
Third Floor - South Tower Box 41
Philadelphia, PA 19104

MAIL TO

Mr. David Myers
Regional Administrator
Federal Railroad Administration
International Plaza Two - Suite 550
Philadelphia, PA 19133

REPORTING OFFICER (signature/title)

Chief Engineer
Communications and Signals

A failure should not be counted more than one time in items 1, 2, 3 and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

RA - Automatic	EM - Electromechanical
AB - Automatic Block	EP - Electropneumatic
ACS - Automatic Cab Signal	FP - False Proceed
APB - Absolute Permissive Block	MB - Manual Block
ATC - Automatic Train Control	M - Mechanical
ATS - Automatic Train Stop	P - Pneumatic
CL - Color Light	PL - Position Light
CPL - Color Position Light	SA - Semiautomatic
E - Electric	TC - Traffic Control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
1. BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input type="checkbox"/> TC				
2. INTERLOCKING <input type="checkbox"/> AUTOMATIC <input checked="" type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL	9/24/99	Commuter Rail Train	Loop Interlocking 14E	Boston, MA
3. AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
4. OTHER (specify)				

NATURE AND CAUSE OF FAILURE/CORRECTIVE ACTION TAKEN

Commuter Rail Road Foreman reported to ADE C&S Commuter the 14E Signal at Loop Interlockings displayed an Approach Medium into a Slow Approach at the 14E at Broad Interlocking. Investigation revealed that a circuit design error from a field change that occurred on March 5, 1999 was the result of improper displayed aspect on 14E at Loop. Circuitry was changed, tests completed and signal system returned to service. Investigation being conducted to determine responsibility.

(If more space is required, continue on reverse)