

DEPARTMENT OF TRANSPORTATION
FEDERAL RAILROAD ADMINISTRATION

FALSE PROCEED SIGNAL REPORT

REPORT FOR (month/year)

July, 1995

DATE

July 15, 1995

REPORTING CARRIER (railroad & region or division)

CSX Transportation

- System -

REPORTING OFFICER (signature/title)

Chief Engr.-Train Control

All railroads subject to Regulations of the Federal Railroad Administration shall submit a false proceed signal report, original only, to the Federal Railroad Administration within five days after a false proceed occurs. If no false proceed occurs during any calendar month, a report showing "No Failures" must be filed within ten days after the end of the month.

Copies of this form will be furnished upon request to the Department of Transportation, Federal Railroad Administration, Office of Safety, Washington, D.C. 20590

MAIL TO

Director of Railroad Safety
Federal Railroad Administration
Suite 440, North Tower
1720 Peachtree Road, NW
Atlanta, Georgia 30309

A failure should not be counted more than one time in items 1, 2, 3, and 4; the failure should be classified under the basic system or appliance of which it forms an essential part. E.g.; assume grounds cause a block signal to indicate a false proceed causing corresponding indications of a cab signal system on each train approaching this point, such failures should be included in item 1, Block Systems.

A false proceed failure is a failure of a system, device or appliance to indicate or function as intended which results in less restriction than intended.

The following abbreviations may be used in the report.

- A—Automatic
- AB—Automatic block
- ACS—Automatic cab signal
- APB—Absolute permissive block
- ATC—Automatic train control
- ATS—Automatic train stop
- CL—Color light
- CPL—Color position light
- E—Electric
- EM—Electromechanical
- EP—Electropneumatic
- FP—False proceed
- MB—Manual block
- M—Mechanical
- P—Pneumatic
- PL—Position light
- SA—Semiautomatic
- TC—Traffic control

TYPE OF SYSTEM	DATE	LOCOMOTIVE NUMBER	DEVICE THAT FAILED	LOCATION (city and state)
¹ BLOCK SYSTEMS <input type="checkbox"/> AB <input type="checkbox"/> APB <input checked="" type="checkbox"/> TC	6/30/95	Train Q31728	Signal 2001	W. Va Keyser Station, PA
² INTERLOCKING <input type="checkbox"/> REMOTE <input type="checkbox"/> MANUAL				
³ AUTOMATIC SYSTEMS <input type="checkbox"/> ATS <input type="checkbox"/> ATC <input type="checkbox"/> ACS				
⁴ OTHER (specify)				

NATURE AND CAUSE OF FAILURE / CORRECTIVE ACTION TAKEN

On June 30, 1995, Train Q-31728 reported receiving two yellows and a marker at Signal 2001 with crossover at Keyser Station line from #1 to #2.

The signal system was removed from service. Signal personnel performed all operational tests and discovered the RE circuit was lodged with the YE circuit. Repairs and additional operational checks were made.

Signal system is not functioning as intended and is returned to service.

Faxed to Reg. 2

(If more space is required, continue on reverse)